

FIG. 1




FIG. 2




FIG. 3




FIG. 4B




FIG. 4C




FIG. 4D





FIG. 4A



16

18

17

14

15

19

FIG. 5




FIG. 6




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 7A




FIG. 8




FIG. 9




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 10D




FIG. 11




FIG. 12




FIG. 13A




FIG. 13B




FIG. 13C




FIG. 13D




FIG. 14




FIG. 15




FIG. 16B




FIG. 16C




FIG. 16D




FIG. 16E

B	B1	B2	B3	B4
X	4	9	16	25

Wire area range
B (μm^2) and contact
area X (μm^2) to be
determined as error

FIG. 16A




FIG. 17




FIG. 18




FIG. 19B




FIG. 19E

67

B	B1	B2	B3	B4
C	1	2	4	9

Wire area range B (μm^2)
and contact number C
to be determined as error

FIG. 19C




FIG. 19A





FIG. 19D



65

66 61

64

FIG. 20




FIG. 21




FIG. 22A




FIG. 22B




FIG. 22C




FIG. 22D




FIG. 22E

L3	W1	W2	W3	W4
C	4	6	8	10

Wire width L3 (μm)
and contact number C
to be determined
as error

77

72

73

74

FIG. 23




FIG. 24




FIG. 25A




FIG. 25E

87

L4	W1	W2	W3	W4
X	1	2	4	8

Wire width L4 (μm)
and contact area X to
be determined as error

FIG. 25B




FIG. 25C




FIG. 25D




FIG. 26




FIG. 27




FIG. 28B




FIG. 28D




FIG. 28A 92






FIG. 28C 94




91

93

FIG. 29E



99 FIG. 29B



95 FIG. 29D




FIG. 29A 92





FIG. 29C 94



91

93






FIG. 31





FIG. 32










FIG. 34




FIG. 35




FIG. 36B




FIG. 36D




FIG. 36A





FIG. 36C



111

113

115

116

112

114

FIG. 37E




FIG. 37D




FIG. 37B




FIG. 37A





FIG. 37C



111

113

FIG. 38B




FIG. 38D




FIG. 38A





FIG. 38C



120

FIG. 39A




FIG. 39B




FIG. 39C




FIG. 39D





FIG. 39E

FIG. 40




FIG. 41




FIG. 42B




FIG. 42D




FIG. 42A




FIG. 42C




FIG. 43A




FIG. 43B




FIG. 43C




FIG. 43D




FIG. 44




FIG. 45




FIG. 46A




FIG. 46B




FIG. 46C




FIG. 46D

